ABSTRACT

A method of manufacturing an oxide superconductive wire includes the step of positioning a metal tape [[(6)]] in a position at a distance (L) of at most 100 mm from a target [[(7)]] for generating an oxide, and the step of forming an oxide superconductive layer on the metal tape [[(6)]] using a vapor deposition method while transferring the metal tape [[(6)]] at a transfer speed of at least 5 m/h with keeping the distance (L) between the metal tape [[(6)]] and the target [[(7)]] of at most 100 mm.